





Spare Parts / Ersatzteile / Pièces de recharge / Pezzi di Ricambio / Piezas de requesto /
 Parte de reposição / Reserveonderdelen / Reservdelar / Reservedeler / Varaosat /
 Vraosat / Varahlutir / Ανταλλακτικά / Yedek Parçalar / Náhradní díly / Náhradné diely /
 Nadomestni deli / Резервни части / Запчасти / Części Zapasowe / Piese de schimb /
 Rendelhető alkatrészek / Запасні частини / Резервни делови / Резервни делови /
 Резервни делови / Atsarginių dalių / Tellitavad varuosad / Rezervnyj daju

XX = AA,AD

- 1 A 963 313 XX
- 2 A 963 054 NU
- 3 A 963 309 NU
- 4 B 960 862 XX
- 6 A 963 314 NU
- 7 A 963 785 NU
- 10 A 963 788 NU
- 11 A 963 324 NU
- 13 A 961 118 NU
- 15 B 960 754 XX
- 16 A 960 949 NU
- 17 A 963 357 XX
- 18 A 963 404 NU
- 19 A 961 230 XX




CERAMIX BLUE



A 5658 ..








0211 / A 866 395
 (+ A 865 612)
 Made in Germany

	P	bar				Q (3 bar)
	T	°C				l/min
						5



Ideal Standard
 Roentgenstrasse 9
 54516 Wittlich
 Germany





P	T	°C	1	2	3	4	5	6	7	8
			°C	°C	°C	°C	°C	°C	°C	°C
0,3 MPa 3 bar	50°C	15°C	47,4	47	44,5	39,9	35,7	33,9	30,7	29,6
	65°C	15°C	61,3	60,7	57,2	50,6	44,6	41,9	37,4	35,9
	85°C	15°C	79,8	79	74	64,8	56,4	52,7	46,3	44,3